

ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE ____ OF ____



Customer Name: <u>Homeca Recycling and Demolitions</u>	Project Name: <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u>
Contact: <u>Melvin Feliciano</u>	Total Samples: <u>17</u> Job Number: <u>ENJ-1161</u>
Phone / Fax/Email: <u>787-426-1597</u>	Worker Name: <u>Eliezer Caraballo</u> Worker ID: <u>ASB-0614-0253-AW</u>
Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u>	Worker Name: <u>Alexis Joel</u> Worker ID: <u>ASB-0414-0119-AW</u>
Analized By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u>	Worker Name: _____ Worker ID: _____
AIHA Lab ID: <u>199763</u>	Worker Name: _____ Worker ID: _____

Project Description: Cleaning Rooms # 11 & 10.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS16071401	Jul-16-14	1161-160714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS16071402	Jul-16-14	1161-160714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS16071403	Jul-16-14	1161-160714-ASB-JS-03	Eliezer Caraballo, Cleaning Room # 11	LV-5087	7:20	7:50	1.6	1.6	1.6	48.0	X			30	E
JS16071404	Jul-16-14	1161-160714-ASB-JS-04	Eliezer Caraballo, Cleaning Room # 11	LV-5087	7:51	11:46	1.6	1.6	1.6	376.0	X			235	PRCE
JS16071405	Jul-16-14	1161-160714-ASB-JS-05	Eliezer Caraballo, Cleaning Room # 11	LV-5087	13:20	15:39	1.6	1.5	1.5	208.5	X			139	PRCE
JS16071406	Jul-16-14	1161-160714-ASB-JS-06	Alexis Joel, Bag Out Room # 10	LV-5093	10:06	12:00	1.6	1.6	1.6	182.4	X			114	PRCE
JS16071407	Jul-16-14	1161-160714-ASB-JS-07	Alexis Joel, Bag Out Room # 10	LV-5093	13:26	15:23	1.6	1.3	1.3	152.1	X			117	PRCE
JS16071408	Jul-16-14	1161-160714-ASB-JS-08	Inside Room # 11	LV-2022	7:21	11:47	2.0	2.0	2.0	532.0	X			266	CE
JS16071409	Jul-16-14	1161-160714-ASB-JS-09	Inside Room # 11	LV-2022	13:21	15:40	2.0	2.0	2.0	278.0	X			139	CE

Turn Around Time: Normal: 7 days <u>X</u>	Rush: 24 hours _____	Rush: 16 hours _____			
Sampling Collected by: _____	Relinquished by: _____	Received by: _____	Received by: _____	Delivery to Lab by: _____	Received at Lab by: _____
Jose A Santos					Jose A Santos
Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____
Jul-16-14					Jul-16-14



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE ____ OF ____



Environmental Services, Inc.

Customer Name: <u>Homeca Recycling and Demolitions</u>		Project Name: <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u>	
Contact: <u>Melvin Feliciano</u>		Total Samples: <u>17</u> Job Number: <u>ENJ-1161</u>	
Phone / Fax/Email: <u>787-426-1597</u>		Worker Name: <u>Eliezer Caraballo</u> Worker ID: <u>ASB-0614-0253-AW</u>	
Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u>		Worker Name: <u>Alexis Joel</u> Worker ID: <u>ASB-0414-0119-AW</u>	
Analized By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u>		Worker Name: _____ Worker ID: _____	
AIHA Lab ID: <u>199763</u>		Worker Name: _____ Worker ID: _____	
Project Description: <u>Cleaning Rooms # 11 & 10.</u>			

JS16071410	Jul-16-14	1161-160714- ASB-JS-10	Inside Room # 10	LV-2019	10:07	12:02	2.0	2.0	2.0	230.0	X			115	CE
JS16071411	Jul-16-14	1161-160714- ASB-JS-11	Inside Room # 10	LV-2019	13:27	15:25	2.0	2.0	2.0	236.0	X			118	CE
JS16071412	Jul-16-14	1161-160714- ASB-JS-12	Outside Room # 11 (Decom)	LV-5052	7:22	11:48	2.5	2.5	2.5	665.0	X			266	OS
JS16071413	Jul-16-14	1161-160714- ASB-JS-13	Outside Room # 11 (Decom)	LV-5052	13:22	15:41	2.5	2.3	2.3	319.7	X			139	OS
JS16071414	Jul-16-14	1161-160714- ASB-JS-14	Outside Room # 10 (Decom)	LV-6268	10:08	12:03	2.5	2.5	2.5	287.5	X			115	OS
JS16071415	Jul-16-14	1161-160714- ASB-JS-15	Outside Room # 10 (Decom)	LV-6268	13:28	15:26	2.5	2.4	2.4	283.2	X			118	OS
JS16071416	Jul-16-14	1161-160714- ASB-JS-16	Outside (Dumpster)	LV-1047	10:09	12:05	2.5	2.5	2.5	290.0	X			116	OS
JS16071417	Jul-16-14	1161-160714- ASB-JS-17	Outside (Dumpster)	LV-1047	13:29	15:27	2.5	2.3	2.3	271.4	X			118	OS

Turn Around Time: Normal: 7 days <u>X</u>		Rush: 24 hours _____		Rush: 16 hours _____		
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____
Jul-16-14						Jul-16-14

ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

Environmental Services, Inc.


Environmental Services, Inc.

Customer Name: Homeca Recycling and Demolitions Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-16-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Eliezer Caraballo Worker Name: Alexis Joel Worker Name: _____ Worker Name: _____	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo Total Samples: 17 Job Number: ENJ-1161 Custody Record #: _____ Collected ID: ASB-0912-0558-MS Delivery Date: Jul-17-14 Received Date: Jul-17-14 AIHA Lab ID: 199763 Worker ID: ASB-0614-0253-AW Worker ID: ASB-0414-0119-AW Worker ID: 0 Worker ID: 0
--	--

Project Description: Cleaning Rooms # 11 & 10.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-160714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-160714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-160714-ASB-JS-03	Eliezer Caraballo, Cleaning Room # 11	E	7:20	7:50	1.6	48.0	100	4	5.1	0.0409	0.0562	< 0.0562	< 0.0175
1161-160714-ASB-JS-04	Eliezer Caraballo, Cleaning Room # 11	PRCE	7:51	11:46	1.6	376.0	100	8.5	10.8	0.0111	0.0072	0.0111	
1161-160714-ASB-JS-05	Eliezer Caraballo, Cleaning Room # 11	PRCE	13:20	15:39	1.5	208.5	100	12.5	15.9	0.0294	0.0129	0.0294	
1161-160714-ASB-JS-06	Alexis Joel, Bag Out Room # 10	PRCE	10:06	12:00	1.6	182.4	100	25	31.8	0.0672	0.0148	0.0672	
1161-160714-ASB-JS-07	Alexis Joel, Bag Out Room # 10	PRCE	13:26	15:23	1.3	152.1	100	29	36.9	0.0935	0.0178	0.0935	0.0388

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.


Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
--	---	--	-------------------



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolitions	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo
Contact: Melvin Feliciano	Total Samples: 17 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Custody Record #:
Sampling Date: Jul-16-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jul-17-14
Delivery By: Jose A Santos	Received Date: Jul-17-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: ASB-0614-0253-AW
Worker Name: Eliezer Caraballo	Worker ID: ASB-0414-0119-AW
Worker Name: Alexis Joel	Worker ID: 0
Worker Name:	Worker ID: 0
Worker Name:	Worker ID: 0

Cleaning Rooms # 11 & 10.

Project Description:

Date: Jul-16-14						Date:							
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-160714-ASB-JS-08	Inside Room # 11	CE	7:21	11:47	2.0	532.0	100	8.5	10.8	0.0078	0.0051	0.0078	
1161-160714-ASB-JS-09	Inside Room # 11	CE	13:21	15:40	2.0	278.0	100	11.5	14.6	0.0203	0.0097	0.0203	
1161-160714-ASB-JS-10	Inside Room # 10	CE	10:07	12:02	2.0	230.0	100	27	34.4	0.0576	0.0117	0.0576	
1161-160714-ASB-JS-11	Inside Room # 10	CE	13:27	15:25	2.0	236.0	100	29.5	37.6	0.0613	0.0114	0.0613	
1161-160714-ASB-JS-12	Outside Room # 11 (Decom)	OS	7:22	11:48	2.5	665.0	100	4.5	5.7	0.0033	0.0041	< 0.0041	
1161-160714-ASB-JS-13	Outside Room # 11 (Decom)	OS	13:22	15:41	2.3	319.7	100	6.5	8.3	0.0100	0.0084	0.0100	
1161-160714-ASB-JS-14	Outside Room # 10(Decom)	OS	10:08	12:03	2.5	287.5	100	7.5	9.6	0.0128	0.0094	0.0128	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: Jul-16-14		Date:	

ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolitions Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-16-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Eliezer Caraballo Worker Name: Alexis Joel Worker Name: _____ Worker Name: _____	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo Total Samples: 17 Job Number: ENJ-1161 Custody Record #: _____ Collected ID: ASB-0912-0558,MS Delivery Date: Jul-17-14 Received Date: Jul-17-14 AIHA Lab ID: 199763 Worker ID: _____ Worker ID: _____ Worker ID: _____ Worker ID: _____
--	--


Cleaning Rooms # 11 & 10.

Project Description:

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-160714-ASB-JS-15	Outside Room # 10 (Decom)	OS	13:28	15:26	2.4	283.2	100	10	12.7	0.0173	0.0095	0.0173	
1161-160714-ASB-JS-16	Outside (Dumpster)	OS	10:09	12:05	2.5	290.0	100	21	26.8	0.0355	0.0093	0.0355	
1161-160714-ASB-JS-17	Outside (Dumpster)	OS	13:29	15:27	2.4	283.2	100	33	42.0	0.0571	0.0095	0.0571	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: _____	Date: _____		




ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE ____ OF ____



Customer Name: <u>Homeca Recycling and Demolitions</u>	Project Name: <u>Esc Jorge Lucas Valdivieso 1 Unidad</u>
Contact: <u>Norma Collazo</u>	Total Samples: <u>6</u> Job Number: <u>ENJ 1161</u>
Phone / Fax/Email: <u>787-373-6722</u>	Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u>	Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
Analyzed By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u>	Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
AIHA Lab ID: <u>199763</u>	Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>

Project Description: Backgrounds Collected In Room # 9 and Bathrooms .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lea Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS16071401	Jul-16-14	1161-160714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS16071402	Jul-16-14	1161-160714-ASB-JS-02	Field Blank II	-----	----		----	----	----	---	X			---	FB
JS16071403	Jul-16-14	1161-160714-ASB-JS-03	Background Collected in room # 9 (East)	HV-6271	9:32	12:20	10.0	10.0	10.0	1680.0	X			168	BG
JS16071404	Jul-16-14	1161-160714-ASB-JS-04	Background Collected in room # 9 (West)	HV-5944	9:33	12:21	10.0	10.0	10.0	1680.0	X			168	BG
JS16071405	Jul-16-14	1161-160714-ASB-JS-05	Background Collected in Boys Bathroom (Center)	HV-6271	12:28	14:26	10.0	10.0	10.0	1180.0	X			118	BG
JS16071406	Jul-16-14	1161-160714-ASB-JS-06	Background Collected in Girls Bathroom (Center)	HV-5944	12:29	14:27	10.0	10.0	10.0	1180.0	X			118	BG

Turn Around Time: Normal: 7 days X Rush: 24 hours Rush: 16 hours

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-16-14						

Customer Name: Homeca Recycling and Demolitions Contact: Norma Collazo Phone / Fax/Email: 787-373-6722 Sampling Date: Jul-16-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: N/A Worker Name: N/A Worker Name: N/A Worker Name: N/A	Project Name: Esc Jorge Lucas Valdivieso 1 Unidad Total Samples: 6 Job Number: ENJ-1161 Custody Record #: Collected ID: ASB-0912-0558-MS Delivery Date: Jul-17-14 Received Date: Jul-17-14 AIHA Lab ID: 199763 Worker ID: N/A Worker ID: N/A Worker ID: N/A Worker ID: N/A
---	--


Project Description: Backgrounds Collected In Room # 9 and Bathrooms .

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-160714-ASB-JS-01	Field Blank I	FB											
1161-160714-ASB-JS-02	Field Blank II	FB											
1161-160714-ASB-JS-03	Background Collected in room # 9 (East)	BG	9:32	12:20	10.0	1680.0	100	37.5	47.8	0.0109	0.0016	0.0109	<
1161-160714-ASB-JS-04	Background Collected in room # 9 (West)	BG	9:33	12:21	10.0	1680.0	100	31	39.5	0.0090	0.0016	0.0090	
1161-160714-ASB-JS-05	Background Collected in Boys Bathroom (Center)	BG	12:28	14:26	10.0	1180.0	100	29.5	37.6	0.0123	0.0023	0.0123	
1161-160714-ASB-JS-06	Background Collected in Girls Bathroom (Center)	BG	12:29	14:27	10.0	1180.0	100	22.5	28.7	0.0094	0.0023	0.0094	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal
 T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787 507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: Jul-16-14	Date:		

Customer Name: Homeca Recycling and Demolitions					Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo										
Contact: Melvin Feliciano					Total Samples: 19					Job Number: ENJ-1161					
Phone / Fax/Email: 787-426-1597					Worker Name: Hector Montañez					Worker ID: ASB-1013-0416-AW					
Collected By: Jose A Santos ASB-0912-0558-MS					Worker Name: Felix Valentin					Worker ID: ASB-1013-0415-AW					
Analized By Lab: Altol Chemical Environmental Laboratory, Inc.					Worker Name:					Worker ID:					
AIHA Lab ID: 199763					Worker Name:					Worker ID:					
Project Description: Cleaning Bathrooms, Rooms 11 , 10 and Bag Out.															
JS17071410	Jul-17-14	1161-170714-ASB-JS-10	Inside Room # 10	LV-2019	7:35	11:57	2.0	2.0	2.0	524.0	X			262	CE
JS17071411	Jul-17-14	1161-170714-ASB-JS-11	Inside Room # 10	LV-2019	13:28	15:23	2.0	2.0	2.0	230.0	X			115	CE
JS17071412	Jul-17-14	1161-170714-ASB-JS-12	Inside Boys Bathroom	LV-5052	7:38	12:05	2.0	2.0	2.0	534.0	X			267	CE
JS17071413	Jul-17-14	1161-170714-ASB-JS-13	Inside Girls Bathroom	LV-5052	13:36	15:29	2.0	2.0	2.0	226.0	X			113	CE
JS17071414	Jul-17-14	1161-170714-ASB-JS-14	Outside Room # 11 (Decom)	LV-6268	7:32	11:52	2.5	2.5	2.5	650.0	X			260	OS
JS17071415	Jul-17-14	1161-170714-ASB-JS-15	Outside Room # 11 (Decom)	LV-6268	13:24	15:21	2.5	2.3	2.3	269.1	X			117	OS
JS17071416	Jul-17-14	1161-170714-ASB-JS-16	Outside Room # 10 (Decom)	LV-1047	7:36	11:58	2.5	2.5	2.5	655.0	X			262	OS
JS17071417	Jul-17-14	1161-170714-ASB-JS-17	Outside Room # 10 (Decom)	LV-1047	13:29	15:26	2.5	2.4	2.4	280.8	X			117	OS
JS17071418	Jul-17-14	1161-170714-ASB-JS-18	Outside (Dumpster)	LV-1052	7:55	12:10	2.5	2.5	2.5	637.5	X			255	OS
Turn Around Time: Normal: 7 days <u> X </u> Rush: 24 hours <u> </u> Rush: 16 hours <u> </u>															
Sampling Collected by:		Relinquished by:		Received by:		Relinquished by:		Received by:		Delivery to Lab by		Received at Lab by			
Jose A Santos												Jose A Santos			
Date: Time:		Date: Time:		Date: Time:		Date: Time:		Date: Time:		Date: Time:		Date: Time:			
Jul-17-14												Jul-17-14			
Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos	Lead	Minutes	SAMPLE TYPE	
					START	STOP	Initial	Final	Avg.		PCM	TEM	Air		



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE ____ OF ____



Environmental Services, Inc.

Customer Name: Homeca Recycling and Demolitions	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo
Contact: Melvin Feliciano	Total Samples: 19 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Worker Name: Hector Montañez Worker ID: ASB-1013-0416-AW
Collected By: Jose A Santos ASB-0912-0558-MS	Worker Name: Felix Valentin Worker ID: ASB-1013-0415-AW
Analized By Lab: Altol Chemical Environmental Laboratory, Inc.	Worker Name: _____ Worker ID: _____
AIHA Lab ID: 199763	Worker Name: _____ Worker ID: _____

Project Description: Cleaning Bathrooms, Rooms 11 , 10 and Bag Out.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS17071401	Jul-17-14	1161-170714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS17071402	Jul-17-14	1161-170714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS17071403	Jul-17-14	1161-170714-ASB-JS-03	Felix Valentin, Cleaning Room # 11	LV-5087	7:30	8:01	1.6	1.6	1.6	49.6	X			31	E
JS17071404	Jul-17-14	1161-170714-ASB-JS-04	Felix Valentin, Cleaning Room # 11	LV-5087	8:02	11:50	1.6	1.6	1.6	364.8	X			228	PRCE
JS17071405	Jul-17-14	1161-170714-ASB-JS-05	Felix Valentin, Cleaning Room # 11	LV-5087	13:22	15:19	1.6	1.4	1.4	163.8	X			117	PRCE
JS17071406	Jul-17-14	1161-170714-ASB-JS-06	Hector Montañez, Cleaning Room # 10 and BagOut.	LV-5093	7:34	11:56	1.6	1.6	1.6	419.2	X			262	PRCE
JS17071407	Jul-17-14	1161-170714-ASB-JS-07	Hector Montañez, Cleaning Room # 10 and BagOut.	LV-5093	13:26	15:22	1.6	1.4	1.4	162.4	X			116	PRCE
JS17071408	Jul-17-14	1161-170714-ASB-JS-08	Inside Room # 11	LV-2022	7:31	11:51	2.0	2.0	2.0	520.0	X			260	CE
JS17071409	Jul-17-14	1161-170714-ASB-JS-09	Inside Room # 11	LV-2022	13:23	15:20	2.0	2.0	2.0	234.0	X			117	CE

Turn Around Time: Normal: 7 days X Rush: 24 hours Rush: 16 hours

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-17-14						Jul-17-14



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolitions	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo
Contact: Melvin Feliciano	Total Samples: 19 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Custody Record #:
Sampling Date: Jul-17-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jul-18-14
Delivery By: Jose A Santos	Received Date: Jul-18-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: ASB-1013-0416-AW
Worker Name: Hector Montañez	Worker ID: ASB-1013-0415-AW
Worker Name: Felix Valentin	Worker ID: 0
Worker Name: 0	Worker ID: 0
Worker Name: 0	Worker ID: 0

Project Description: Cleaning Bathrooms, Rooms 11 , 10 and Bag Out.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-170714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-170714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-170714-ASB-JS-03	Felix Valentin, Cleaning Room # 11	E	7:30	8:01	1.6	49.6	100	4.5	5.7	0.0445	0.0544	< 0.0544	< 0.0204
1161-170714-ASB-JS-04	Felix Valentin, Cleaning Room # 11	PRCE	8:02	11:50	1.6	364.8	100	11	14.0	0.0148	0.0074	0.0148	
1161-170714-ASB-JS-05	Felix Valentin, Cleaning Room # 11	PRCE	13:22	15:19	1.4	163.8	100	13.5	17.2	0.0404	0.0165	0.0404	
1161-170714-ASB-JS-06	Hector Montañez, Cleaning Room # 10 and BagOut.	PRCE	7:34	11:56	1.6	419.2	100	30	38.2	0.0351	0.0064	0.0351	
1161-170714-ASB-JS-07	Hector Montañez, Cleaning Room # 10 and BagOut.	PRCE	13:26	15:22	1.4	162.4	100	33	42.0	0.0997	0.0166	0.0997	0.0432

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature:	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
---	------------	---	------------



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolitions	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo
Contact: Melvin Feliciano	Total Samples: 19 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Custody Record #:
Sampling Date: Jul-17-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jul-18-14
Delivery By: Jose A Santos	Received Date: Jul-18-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: ASB-1013-0416-AW
Worker Name: Hector Montañez	Worker ID: ASB-1013-0415-AW
Worker Name: Felix Valentin	Worker ID: 0
Worker Name: 0	Worker ID: 0

Project Description: Cleaning Bathrooms, Rooms 11, 10 and Bag Out.

Date: Jul-17-14						Date:							
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-170714-ASB-JS-08	Inside Room # 11	CE	7:31	11:51	2.0	520.0	100	7.5	9.6	0.0071	0.0052	0.0071	
1161-170714-ASB-JS-09	Inside Room # 11	CE	13:23	15:20	2.0	234.0	100	9.5	12.1	0.0199	0.0115	0.0199	
1161-170714-ASB-JS-10	Inside Room # 10	CE	7:35	11:57	2.0	524.0	100	19.5	24.8	0.0183	0.0052	0.0183	
1161-170714-ASB-JS-11	Inside Room # 10	CE	13:28	15:23	2.0	230.0	100	24.5	31.2	0.0522	0.0117	0.0522	
1161-170714-ASB-JS-12	Inside Boys Bathroom	CE	7:38	12:05	2.0	534.0	100	23.5	29.9	0.0216	0.0051	0.0216	
1161-170714-ASB-JS-13	Inside Girls Bathroom	CE	13:36	15:29	2.0	226.0	100	28.5	36.3	0.0618	0.0119	0.0618	
1161-170714-ASB-JS-14	Outside Room # 11 (Decom)	OS	7:32	11:52	2.5	650.0	100	3.5	4.5	0.0026	0.0042	0.0042	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal
T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature:	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature: _____
Date: Jul-17-14		Date: _____	



ALTOL ENVIRONMENTAL SERVICES, INC.
PO BOX 359 MERCEDITA, PR 00715-0359
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS




Customer Name: Homeca Recycling and Demolitions	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo
Contact: Melvin Feliciano	Total Samples: 19 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Custody Record #:
Sampling Date: Jul-17-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jul-18-14
Delivery By: Jose A Santos	Received Date: Jul-18-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: ASB-1013-0416-AW
Worker Name: Hector Montañez	Worker ID: ASB-1013-0415-AW
Worker Name: Felix Valentin	Worker ID: 0
Worker Name:	Worker ID: 0
Worker Name:	Worker ID: 0

Project Description: Cleaning Bathrooms, Rooms 11 , 10 and Bag Out.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-170714-ASB-JS-15	Outside Room # 11 (Decom)	OS	13:24	15:21	2.3	269.1	100	5.5	7.0	0.0100	0.0100	0.0100	
1161-170714-ASB-JS-16	Outside Room # 10 (Decom)	OS	7:36	11:58	2.5	655.0	100	23	29.3	0.0172	0.0041	0.0172	
1161-170714-ASB-JS-17	Outside Room # 10 (Decom)	OS	13:29	15:27	2.4	283.2	100	35	44.6	0.0606	0.0095	0.0606	
1161-170714-ASB-JS-18	Outside (Dumpster)	OS	7:55	12:10	2.5	637.5	100	16	20.4	0.0123	0.0042	0.0123	
1161-170714-ASB-JS-19	Outside (Dumpster)	OS	13:32	15:05	2.3	213.9	100	26.5	33.8	0.0608	0.0126	0.0608	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date:		Date:	

**ALTOL ENVIRONMENTAL SERVICES, INC.**

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE ____ OF ____



Customer Name: Homeca Recycling and Demolitions					Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo										
Contact: Melvin Feliciano					Total Samples: 16					Job Number: ENJ-1161					
Phone / Fax/Email: 787-426-1597					Worker Name: Luis N Ortiz					Worker ID: ASB-0414-0117-AW					
Collected By: Jose A Santos ASB-0912-0558-MS					Worker Name: Eliceo Caraballo					Worker ID: ASB-1213-0505-AW					
Analized By Lab: Altol Chemical Environmental Laboratory, Inc.					Worker Name: _____					Worker ID: _____					
AIHA Lab ID: 199763					Worker Name: _____					Worker ID: _____					
Project Description: Cleaning Girls Bathroom, Rooms 10 , and Room 9 .															
Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS18071401	Jul-18-14	1161-180714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS18071402	Jul-18-14	1161-180714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS18071403	Jul-18-14	1161-180714-ASB-JS-03	Luis N Ortiz, Cleaning Room # 10	LV-5087	7:32	8:05	1.6	1.6	1.6	52.8	X			33	E
JS18071404	Jul-18-14	1161-180714-ASB-JS-04	Luis N Ortiz, Cleaning Room # 10	LV-5087	8:06	11:36	1.6	1.6	1.6	336.0	X			210	PRCE
JS18071405	Jul-18-14	1161-180714-ASB-JS-05	Luis N Ortiz, Cleaning Room # 10	LV-5087	13:30	15:18	1.6	1.4	1.4	151.2	X			108	PRCE
JS18071406	Jul-18-14	1161-180714-ASB-JS-06	Eliceo Caraballo, Cleaning Room # 9	LV-5093	9:40	11:42	1.6	1.6	1.6	195.2	X			122	PRCE
JS18071407	Jul-18-14	1161-180714-ASB-JS-07	Eliceo Caraballo, Cleaning Room # 9	LV-5093	13:36	15:28	1.6	1.4	1.4	156.8	X			112	PRCE
JS18071408	Jul-18-14	1161-180714-ASB-JS-08	Inside Room # 10	LV-2022	7:33	11:37	2.0	2.0	2.0	488.0	X			244	CE
JS18071409	Jul-18-14	1161-180714-ASB-JS-09	Inside Room # 10	LV-2022	13:31	15:19	2.0	2.0	2.0	216.0	X			108	CE
Turn Around Time: Normal: 7 days <u> X </u> Rush: 24 hours _____ Rush: 16 hours _____															
Sampling Collected by:		Relinquished by:		Received by:		Relinquished by:		Received by:		Delivery to Lab by:		Received at Lab by:			
Jose A Santos												Jose A Santos			
Date: Time:		Date: Time:		Date: Time:		Date: Time:		Date: Time:		Date: Time:		Date: Time:			
Jul-18-14												Jul-18-14			



Environmental Services, Inc.

[illegible]



ALTOL ENVIRONMENTAL SERVICES, INC.
PO BOX 359 MERCEDITA, PR 00715-0359
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS




Customer Name: Homeca Recycling and Demolitions							Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo						
Contact: Melvin Feliciano							Total Samples: 16 Job Number: ENJ-1161						
Phone / Fax/Email: 787-426-1597							Custody Record #:						
Sampling Date: Jul-18-14 Analytical Method: NIOSH 7400							Collected ID: ASB-0912-0558-MS						
Collected By: Jose A Santos							Delivery Date: Jul-19-14						
Delivery By: Jose A Santos							Received Date: Jul-19-14						
Received By: Jose A Santos							AIHA Lab ID: 199763						
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.							Worker ID: ASB-0414-0117-AW						
Worker Name: Luis N Ortiz							Worker ID: ASB-1213-0505-AW						
Worker Name: Eliceo Caraballo							Worker ID: 0						
Worker Name: 0							Worker ID: 0						
Worker Name: 0							Worker ID: 0						

Project Description: Cleaning Girls Bathroom, Rooms 10 , and Room 9 .													
--	--	--	--	--	--	--	--	--	--	--	--	--	--

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-180714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-180714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-180714-ASB-JS-03	Luis N Ortiz, Cleaning Room # 10	E	7:32	8:05	1.6	52.8	100	8	10.2	0.0743	0.0511	0.0743	< 0.0213
1161-180714-ASB-JS-04	Luis N Ortiz, Cleaning Room # 10	PRCE	8:06	11:36	1.6	336.0	100	11	14.0	0.0161	0.0080	0.0161	
1161-180714-ASB-JS-05	Luis N Ortiz, Cleaning Room # 10	PRCE	13:30	15:18	1.4	151.2	100	12.5	15.9	0.0405	0.0179	0.0405	
1161-180714-ASB-JS-06	Eliceo Caraballo, Cleaning Room # 9	PRCE	9:40	11:42	1.6	195.2	100	30	38.2	0.0754	0.0138	0.0754	
1161-180714-ASB-JS-07	Eliceo Caraballo, Cleaning Room # 9	PRCE	13:36	15:28	1.4	156.8	100	27.5	35.0	0.0860	0.0172	0.0860	0.0392

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
--	---	--	-------------------



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolitions Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-18-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Luis N Ortiz Worker Name: Eliceo Caraballo Worker Name: _____ Worker Name: _____	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo Total Samples: 16 Job Number: ENJ-1161 Custody Record #: _____ Collected ID: ASB-0912-0558-MS Delivery Date: Jul-19-14 Received Date: Jul-19-14 AIHA Lab ID: 199763 Worker ID: ASB-0414-0117-AW Worker ID: ASB-1213-0505-AW Worker ID: 0 Worker ID: 0
--	--

Project Description: Cleaning Girls Bathroom, Rooms 10 , and Room 9 .	
--	--

Date: Jul-18-14						Date:							
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-180714-ASB-JS-08	Inside Room # 10	CE	7:33	11:37	2.0	488.0	100	8.5	10.8	0.0085	0.0055	0.0085	
1161-180714-ASB-JS-09	Inside Room # 10	CE	13:31	15:19	2.0	216.0	100	11.5	14.6	0.0261	0.0125	0.0261	
1161-180714-ASB-JS-10	Inside Room # 9	CE	9:41	11:43	2.0	244.0	100	22.5	28.7	0.0452	0.0111	0.0452	
1161-180714-ASB-JS-11	Inside Room # 9	CE	13:37	15:29	2.0	224.0	100	27.5	35.0	0.0602	0.0121	0.0602	
1161-180714-ASB-JS-12	Inside Girls Bathroom	CE	8:26	11:57	2.0	422.0	100	25	31.8	0.0291	0.0064	0.0291	
1161-180714-ASB-JS-13	Outside Room # 10 (Decom)	OS	7:35	11:38	2.5	607.5	100	7.5	9.6	0.0061	0.0044	0.0061	
1161-180714-ASB-JS-14	Outside Room # 10 (Decom)	OS	13:32	15:20	2.2	237.6	100	4.5	5.7	0.0093	0.0114	0.0114	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: Jul-18-14		Date:	



ALTOL ENVIRONMENTAL SERVICES, INC.
 PO BOX 359 MERCEDITA, PR 00715-0359
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolitions Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-18-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Luis N Ortiz Worker Name: Eliceo Caraballo Worker Name: _____ 0 Worker Name: _____ 0						Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo Total Samples: 16 Job Number: ENJ-1161 Custody Record #: _____ Collected ID: ASB-0912-0558-MS Delivery Date: Jul-19-14 Received Date: Jul-19-14 AIHA Lab ID: 199763 Worker ID: _____ ASB-0414-0117-AW Worker ID: _____ ASB-1213-0505-AW Worker ID: _____ 0 Worker ID: _____ 0					
Project Description: Cleaning Girls Bathroom, Rooms 10 , and Room 9 .											

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-180714-ASB-JS-15	Outside Room # 9 (Decom)	OS	9:42	11:44	2.5	305.0	100	5.5	7.0	0.0088	0.0089	0.0089	
1161-180714-ASB-JS-16	Outside Room # 9 (Decom)	OS	13:38	15:40	2.4	292.8	100	6.5	8.3	0.0109	0.0092	0.0109	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: _____	Date: _____	Date: _____	Date: _____

**ALTOL ENVIRONMENTAL SERVICES, INC.**

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE ____ OF ____



Customer Name: <u>Homeca Recycling and Demolitions</u>	Project Name: <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u>
Contact: <u>Melvin Feliciano</u>	Total Samples: <u>15</u> Job Number: <u>ENJ-1161</u>
Phone / Fax/Email: <u>787-426-1597</u>	Worker Name: <u>Hector Montañez</u> Worker ID: <u>ASB-1013-0416-AW</u>
Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u>	Worker Name: <u>Ederick Caquias</u> Worker ID: <u>ASB-0813-0297-AW</u>
Analized By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u>	Worker Name: _____ Worker ID: _____
AIHA Lab ID: <u>199763</u>	Worker Name: _____ Worker ID: _____

Project Description: Cleaning Rooms 10 , and 9 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS19071401	Jul-19-14	1161-190714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS19071402	Jul-19-14	1161-190714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS19071403	Jul-19-14	1161-190714-ASB-JS-03	Hector Montañez, Cleaning Room # 10	LV-5093	7:30	8:02	1.6	1.6	1.6	51.2	X			32	E
JS19071404	Jul-19-14	1161-190714-ASB-JS-04	Hector Montañez, Cleaning Room # 10	LV-5093	8:03	10:50	1.6	1.6	1.6	267.2	X			167	PRCE
JS19071405	Jul-19-14	1161-190714-ASB-JS-05	Hector Montañez, Cleaning Room # 10	LV-5093	12:15	13:30	1.6	1.6	1.6	120.0	X			75	PRCE
JS19071406	Jul-19-14	1161-190714-ASB-JS-06	Ederick Caquias, Cleaning Room # 9	LV-5087	7:38	10:54	1.6	1.6	1.6	313.6	X			196	PRCE
JS19071407	Jul-19-14	1161-190714-ASB-JS-07	Ederick Caquias, Cleaning Room # 9	LV-5087	12:20	13:34	1.6	1.6	1.6	118.4	X			74	PRCE
JS19071408	Jul-19-14	1161-190714-ASB-JS-08	Inside Room # 10	LV-2022	7:34	10:51	2.0	2.0	2.0	394.0	X			197	CE
JS19071409	Jul-19-14	1161-190714-ASB-JS-09	Inside Room # 10	LV-2022	12:16	13:31	2.0	2.0	2.0	150.0	X			75	CE

Turn Around Time: Normal: 7 days X Rush: 24 hours _____ Rush: 16 hours _____

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-19-14						Jul-19-14

**ALTOL ENVIRONMENTAL SERVICES, INC.**

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE ____ OF ____



Customer Name: <u>Homeca Recycling and Demolitions</u>					Project Name: <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u>											
Contact: <u>Melvin Feliciano</u>					Total Samples: <u>15</u>						Job Number: <u>ENJ-1161</u>					
Phone / Fax/Email: <u>787-426-1597</u>					Worker Name: <u>Hector Montañez</u>						Worker ID: <u>ASB-1013-0416-AW</u>					
Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u>					Worker Name: <u>Ederick Caquias</u>						Worker ID: <u>ASB-0813-0297-AW</u>					
Analyzed By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u>					Worker Name: _____						Worker ID: _____					
AIHA Lab ID: <u>199763</u>					Worker Name: _____						Worker ID: _____					
Project Description: <u>Cleaning Rooms 10 , and 9 .</u>																
JS19071410	Jul-19-14	1161-190714- ASB-JS-10	Inside Room # 9	LV-2019	7:39	10:55	2.0	2.0	2.0	392.0	X			196	CE	
JS19071411	Jul-19-14	1161-190714- ASB-JS-11	Inside Room # 9	LV-2019	12:21	13:35	2.0	2.0	2.0	148.0	X			74	CE	
JS19071412	Jul-19-14	1161-190714- ASB-JS-12	Outside Room # 10 (Decom)	LV-5052	7:36	10:52	2.5	2.5	2.5	490.0	X			196	OS	
JS19071413	Jul-19-14	1161-190714- ASB-JS-13	Outside Room # 10 (Decom)	LV-5052	12:17	13:32	2.5	2.5	2.5	187.5	X			75	OS	
JS19071414	Jul-19-14	1161-190714- ASB-JS-14	Outside Room # 9 (Decom)	LV-1047	7:40	10:56	2.5	2.5	2.5	490.0	X			196	OS	
JS19071415	Jul-19-14	1161-190714- ASB-JS-15	Outside Room # 9 (Decom)	LV-1047	12:22	13:36	2.5	2.5	2.5	185.0	X			74	OS	
Turn Around Time: Normal: 7 days <u> X </u> Rush: 24 hours _____ Rush: 16 hours _____																
Sampling Collected by:		Relinquished by:		Received by:		Relinquished by:		Received by:		Delivery to Lab by:		Received at Lab by:				
Jose A Santos												Jose A Santos				
Date: _____ Time: _____		Date: _____ Time: _____		Date: _____ Time: _____		Date: _____ Time: _____		Date: _____ Time: _____		Date: _____ Time: _____		Date: _____ Time: _____				
Jul-19-14												Jul-19-14				



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS




Customer Name: Homeca Recycling and Demolitions	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo
Contact: Melvin Feliciano	Total Samples: 15 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Custody Record #:
Sampling Date: Jul-19-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jul-21-14
Delivery By: Jose A Santos	Received Date: Jul-21-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: ASB-1013-0416-AW
Worker Name: Hector Montañez	Worker ID: ASB-0813-0297-AW
Worker Name: Ederick Caquias	Worker ID: 0
Worker Name: 0	Worker ID: 0
Worker Name: 0	Worker ID: 0

Project Description: Cleaning Rooms 10 , and 9 .

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-190714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-190714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-190714-ASB-JS-03	Hector Montañez, Cleaning Room # 10	E	7:30	8:02	1.6	51.2	100	4.5	5.7	0.0431	0.0527	< 0.0527	< 0.0198
1161-190714-ASB-JS-04	Hector Montañez, Cleaning Room # 10	PRCE	8:03	10:50	1.6	267.2	100	14.5	18.5	0.0266	0.0101	0.0266	
1161-190714-ASB-JS-05	Hector Montañez, Cleaning Room # 10	PRCE	12:15	13:30	1.6	120.0	100	11	14.0	0.0450	0.0225	0.0450	
1161-190714-ASB-JS-06	Ederick Caquias, Cleaning Room # 9	PRCE	7:38	10:54	1.6	313.6	100	20.5	26.1	0.0321	0.0086	0.0321	
1161-190714-ASB-JS-07	Ederick Caquias, Cleaning Room # 9	PRCE	12:20	13:34	1.6	118.4	100	19.5	24.8	0.0808	0.0228	0.0808	0.0255

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
--	---	--	-------------------



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolitions Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-19-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Hector Montañez Worker Name: Ederick Caquias Worker Name: _____ 0 Worker Name: _____ 0	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo Total Samples: 15 Job Number: ENJ-1161 Custody Record #: _____ Collected ID: ASB-0912-0558-MS Delivery Date: Jul-21-14 Received Date: Jul-21-14 AIHA Lab ID: 199763 Worker ID: _____ ASB-1013-0416-AW Worker ID: _____ ASB-0813-0297-AW Worker ID: _____ 0 Worker ID: _____ 0
--	--

Project Description: Cleaning Rooms 10 , and 9 .

Date: Jul-19-14						Date:							
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-190714-ASB-JS-08	Inside Room # 10	CE	7:34	10:51	2.0	394.0	100	10.5	13.4	0.0131	0.0069	0.0131	
1161-190714-ASB-JS-09	Inside Room # 10	CE	12:16	13:31	2.0	150.0	100	8	10.2	0.0262	0.0180	0.0262	
1161-190714-ASB-JS-10	Inside Room # 9	CE	7:39	10:55	2.0	392.0	100	19	24.2	0.0238	0.0069	0.0238	
1161-190714-ASB-JS-11	Inside Room # 9	CE	12:21	13:35	2.0	148.0	100	21	26.8	0.0696	0.0182	0.0696	
1161-190714-ASB-JS-12	Outside Room # 10 (Decom)	OS	7:36	10:52	2.5	490.0	100	6	7.6	0.0060	0.0055	0.0060	
1161-190714-ASB-JS-13	Outside Room # 10 (Decom)	OS	12:17	13:32	2.5	187.5	100	8.5	10.8	0.0222	0.0144	0.0222	
1161-190714-ASB-JS-14	Outside Room # 9 (Decom)	OS	7:40	10:56	2.5	490.0	100	5.5	7.0	0.0055	0.0055	0.0055	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: Jul-19-14		Date:	



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS




Customer Name: Homeca Recycling and Demolitions	Project Name: 1 ra Unidad Esc Jorge Lucas Valdiviezo
Contact: Melvin Feliciano	Total Samples: 15 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Custody Record #:
Sampling Date: Jul-19-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jul-21-14
Delivery By: Jose A Santos	Received Date: Jul-21-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: ASB-1013-0416-AW
Worker Name: Hector Montañez	Worker ID: ASB-0813-0297-AW
Worker Name: Ederick Caquias	Worker ID: 0
Worker Name: 0	Worker ID: 0

Project Description: Cleaning Rooms 10 , and 9 .

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-190714-ASB-JS-15	Outside Room # 9 (Decom)	OS	12:22	13:36	2.5	185.0	100	8.5	10.8	0.0225	0.0146	0.0225	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal
T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date:		Date:	



PO BOX 359 MERCEDITA, PR 00715-0359
CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)



Customer Name: Homeca Recycling and Demolition's Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Collected By: Jose A Santos ASB-0912-0558-MS Analyzed By Lab: Altol Chemical Environmental Laboratory, Inc. AIHA Lab ID: 199763	Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso Total Samples: 14 Job Number: ENJ- 1161 Worker Name: Luis N Ortiz Worker ID: ASB-0414-0117-AW Worker Name: Felix Valentin Worker ID: ASB-1013-0415-AW Worker Name: Eliceo Caraballo Worker ID: ASB-1213-0505-AW Worker Name: N/A Worker ID: N/A
--	--

Project Description: Cleaning Rooms # 6 ,9 and Bag Out.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS21071401	Jul-21-14	1161-210714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS21071402	Jul-21-14	1161-210714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS21071403	Jul-21-14	1161-210714-ASB-JS-03	Luis N Ortiz, Cleaning Room # 6	LV-5087	7:40	8:12	1.6	1.6	1.6	51.2	X			32	E
JS21071404	Jul-21-14	1161-210714-ASB-JS-04	Luis N Ortiz, Cleaning Room # 6	LV-5087	8:13	11:56	1.6	1.6	1.6	356.8	X			223	PRCE
JS21071405	Jul-21-14	1161-210714-ASB-JS-05	Luis N Ortiz, Cleaning Room # 6	LV-5087	13:25	15:40	1.6	1.5	1.5	202.5	X			135	PRCE
JS21071406	Jul-21-14	1161-210714-ASB-JS-06	Felix Valentin, Cleaning Room # 9	LV-6124	7:45	12:03	1.6	1.6	1.6	412.8	X			258	PRCE
JS21071407	Jul-21-14	1161-210714-ASB-JS-07	Felix Valentin, Cleaning Room # 9	LV -6124	13:30	15:48	1.6	1.4	1.4	193.2	X			138	PRCE
JS21071408	Jul-21-14	1161-210714-ASB-JS-08	Eliceo Caraballo, Bag Out	LV-5093	13:40	15:18	1.6	1.5	1.5	147.0	X			98	PREX
JS21071409	Jul-21-14	1161-210714-ASB-JS-09	Inside Room # 6	LV-2022	7:41	11:57	2.5	2.5	2.5	640.0	X			256	CE

Turn Around Time: Normal: 7 days <u> X </u> Rush: 24 hours _____ Rush: 16 hours _____							
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:	
Jose A Santos						Jose A Santos	
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	
Jul-21-14						Jul-21-14	



PO BOX 359 MERCEDITA, PR 00715-0359
CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)



Customer Name: <u>Homeca Recycling and Demolition's</u> Contact: <u>Melvin Feliciano</u> Phone / Fax/Email: <u>787-426-1597</u> Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> Analyzed By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u> AIHA Lab ID: <u>199763</u>	Project Name: <u># 1 Unit, Jorge Lucas Perez Valdivieso</u> Total Samples: <u>14</u> Job Number: <u>ENJ- 1161</u> Worker Name: <u>Luis N Ortiz</u> Worker ID: <u>ASB-0414-0117-AW</u> Worker Name: <u>Felix Valentin</u> Worker ID: <u>ASB-1013-0415-AW</u> Worker Name: <u>Eliceo Caraballo</u> Worker ID: <u>ASB-1213-0505-AW</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
--	--

Project Description: Cleaning Rooms # 6 ,9 and Bag Out.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS21071410	Jul-21-14	1161-210714-ASB-JS-10	Inside Room # 6	LV-2022	13:26	15:41	2.5	2.4	2.4	324.0	X			135	CE
JS21071411	Jul-21-14	1161-210714-ASB-JS-11	Inside Room # 9	LV-2019	7:46	12:04	2.5	2.5	2.5	645.0	X			258	CE
JS21071412	Jul-21-14	1161-210714-ASB-JS-12	Inside Room # 9	LV-2019	13:31	15:49	2.5	2.2	2.2	303.6	X			138	CE
JS21071413	Jul-21-14	1161-210714-ASB-JS-13	Outside Room # 6	LV-1056	7:42	11:58	2.5	2.5	2.5	640.0	X			256	OS
JS21071414	Jul-21-14	1161-210714-ASB-JS-14	Outside Room # 6	LV-1056	13:27	15:43	2.5	2.4	2.4	326.4	X			136	OS
JS21071415	Jul-21-14	1161-210714-ASB-JS-15	Outside Room # 9	LV-1047	7:47	12:05	2.5	2.5	2.5	645.0	X			258	OS
JS21071416	Jul-21-14	1161-210714-ASB-JS-16	Outside Room # 9	LV-1047	13:32	15:50	2.5	2.3	2.3	317.4	X			138	OS
JS21071417	Jul-21-14	1161-210714-ASB-JS-17	Outside (Dumpster)	LV-1057	13:43	15:19	2.5	2.5	2.5	240.0	X			96	OS

Turn Around Time: Normal: 7 days X Rush: 24 hours Rush: 16 hours

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-21-14						Jul-21-14



ALTOL ENVIRONMENTAL SERVICES, INC.
 PO BOX 359 MERCEDITA, PR 00715-0359
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolition's Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-21-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Luis N Ortiz Worker Name: Felix Valentin Worker Name: Eliceo Caraballo Worker Name: N/A	Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso Total Samples: 14 Job Number: ENJ-1161 Custody Record #: Collected ID: ASB-0912-0558-MS Delivery Date: Jul-22-14 Received Date: Jul-22-14 AIHA Lab ID: 199763 Worker ID: ASB-0414-0117-AW Worker ID: ASB-1013-0415-AW Worker ID: ASB-1213-0505-AW Worker ID: N/A
--	---

Project Description: Cleaning Rooms # 6, 9 and Bag Out.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-210714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-210714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-210714-ASB-JS-03	Luis N Ortiz, Cleaning Room # 6	E	7:40	8:12	1.6	51.2	100	12	15.3	0.1149	0.0527	0.1149	< 0.0482
1161-210714-ASB-JS-04	Luis N Ortiz, Cleaning Room # 6	PRCE	8:13	11:56	1.6	356.8	100	32.5	41.4	0.0447	0.0076	0.0447	
1161-210714-ASB-JS-05	Luis N Ortiz, Cleaning Room # 6	PRCE	13:25	15:40	1.5	202.5	100	29	36.9	0.0702	0.0133	0.0702	
1161-210714-ASB-JS-06	Felix Valentin, Cleaning Room # 9	PRCE	7:45	12:03	1.6	412.8	100	16.5	21.0	0.0196	0.0065	0.0196	< 0.0248
1161-210714-ASB-JS-07	Felix Valentin, Cleaning Room # 9	PRCE	13:30	15:48	1.4	193.2	100	19.5	24.8	0.0495	0.0140	0.0495	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: Jul-21-14		Date:	



ALTOL ENVIRONMENTAL SERVICES, INC.
PO BOX 359 MERCEDITA, PR 00715-0359
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS




Customer Name: Homeca Recycling and Demolition's							Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso							
Contact: Melvin Feliciano							Total Samples: 14 Job Number: ENJ-1161							
Phone / Fax/Email: 787-426-1597							Custody Record #:							
Sampling Date: Jul-21-14 Analytical Method: NIOSH 7400							Collected ID: ASB-0912-0558-MS							
Collected By: Jose A Santos							Delivery Date: Jul-22-14							
Delivery By: Jose A Santos							Received Date: Jul-22-14							
Received By: Jose A Santos							AIHA Lab ID: 199763							
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.							Worker ID: ASB-0414-0117-AW							
Worker Name: Luis N Ortiz							Worker ID: ASB-1013-0415-AW							
Worker Name: Felix Valentin							Worker ID: ASB-1213-0505-AW							
Worker Name: Eliceo Caraballo							Worker ID: N/A							
Worker Name: N/A														
Project Description: Cleaning Rooms # 6 ,9 and Bag Out.														
Date: Jul-21-14														
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)	
			START	STOP										
1161-210714-ASB-JS-08	Eliceo Caraballo, Bag Out	PREX	13:40	15:18	1.5	147.0	100	29.5	37.6	0.0984	0.0184	0.0984	0.0201	
1161-210714-ASB-JS-09	Inside Room # 6	CE	7:41	11:57	2.5	640.0	100	23	29.3	0.0176	0.0042	0.0176		
1161-210714-ASB-JS-10	Inside Room # 6	CE	13:26	15:41	2.4	324.0	100	18.5	23.6	0.0280	0.0083	0.0280		
1161-210714-ASB-JS-11	Inside Room # 9	CE	7:46	12:04	2.5	645.0	100	15	19.1	0.0114	0.0042	0.0114		
1161-210714-ASB-JS-12	Inside Room # 9	CE	13:31	15:49	2.2	303.6	100	19.5	24.8	0.0315	0.0089	0.0315		
1161-210714-ASB-JS-13	Outside Room # 6	OS	7:42	11:58	2.5	640.0	100	10	12.7	0.0077	0.0042	0.0077		
1161-210714-ASB-JS-14	Outside Room # 6	OS	13:27	15:43	2.4	326.4	100	8.5	10.8	0.0128	0.0083	0.0128		
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.														
Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627					Signature: 		Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229				Signature:			
Date: Jul-21-14							Date:							



ALTOL ENVIRONMENTAL SERVICES, INC.
PO BOX 359 MERCEDITA, PR 00715-0359
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolition's								Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso							
Contact: Melvin Feliciano								Total Samples: 14 Job Number: ENJ-1161							
Phone / Fax/Email: 787-426-1597								Custody Record #:							
Sampling Date: Jul-21-14				Analytical Method: NIOSH 7400				Collected ID: ASB-0912-0558-MS							
Collected By: Jose A Santos								Delivery Date: Jul-22-14							
Delivery By: Jose A Santos								Received Date: Jul-22-14							
Received By: Jose A Santos								AIHA Lab ID: 199763							
Analyzed By: Jose A Santos				Altol Chemical Environmental Laboratory, Inc.				Worker ID: ASB-0414-0117-AW							
Worker Name: Luis N Ortiz								Worker ID: ASB-1013-0415-AW							
Worker Name: Felix Valentin								Worker ID: ASB-1213-0505-AW							
Worker Name: Eliceo Caraballo								Worker ID: N/A							
Worker Name: N/A															
Project Description: Cleaning Rooms # 6 ,9 and Bag Out.															
1161-210714- ASB-JS-15	Outside Room # 9	OS	7:47	12:05	2.5	645.0	100	5	6.4	0.0038	0.0042	0.0042			
1161-210714- ASB-JS-16	Outside Room # 9	OS	13:32	15:50	2.3	317.4	100	6.5	8.3	0.0100	0.0085	0.0100			
1161-210714- ASB-JS-17	Outside (Dumpster)	OS	13:43	15:19	2.5	240.0	100	22	28.0	0.0450	0.0113	0.0450			
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.															
Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627		Signature: 		Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229				Signature:							
Date:		Date:													

Customer Name: <u>Homeca Recycling and Demolition's</u> Contact: <u>Melvin Feliciano</u> Phone / Fax/Email: <u>787-426-1597</u> Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> Analyzed By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u> AIHA Lab ID: <u>199763</u>	Project Name: <u># 1 Unit, Jorge Lucas Perez Valdivieso</u> Total Samples: <u>13</u> Job Number: <u>ENJ- 1161</u> Worker Name: <u>Luis N Ortiz</u> Worker ID: <u>ASB-0414-0117-AW</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
--	---

Project Description: Cleaning of room # 6 and Big basketball court.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS23071401	Jul-23-14	1161-230714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS23071402	Jul-23-14	1161-230714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS23071403	Jul-23-14	1161-230714-ASB-JS-03	Luis N Ortiz, Cleaning Room # 6	LV-6124	7:28	7:59	1.6	1.6	1.6	49.6	X			31	E
JS23071404	Jul-23-14	1161-230714-ASB-JS-04	Luis N Ortiz, Cleaning Room # 6	LV-6124	8:00	11:53	1.6	1.6	1.6	372.8	X			233	PRCE
JS23071405	Jul-23-14	1161-230714-ASB-JS-05	Luis N Ortiz, Cleaning Room # 6	LV-6124	13:20	15:40	1.6	1.5	1.5	210.0	X			140	PRCE
JS23071406	Jul-23-14	1161-230714-ASB-JS-06	Inside Room # 6	LV-5087	7:29	11:54	2.5	2.5	2.5	662.5	X			265	CE
JS23071407	Jul-23-14	1161-230714-ASB-JS-07	Inside Room # 6	LV -5087	13:21	15:41	2.5	2.4	2.4	336.0	X			140	CE
JS23071408	Jul-23-14	1161-230714-ASB-JS-08	Outside Room # 6 (Decom)	LV-5093	7:30	11:55	2.5	2.5	2.5	662.5	X			265	OS
JS23071409	Jul-23-14	1161-230714-ASB-JS-09	Outside Room # 6 (Decom)	LV-5093	13:22	15:42	2.5	2.3	2.3	322.0	X			140	OS

Turn Around Time: Normal: 7 days X Rush: 24 hours Rush: 16 hours

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-23-14						Jul-23-14

Customer Name: <u>Homeca Recycling and Demolition's</u> Contact: <u>Melvin Feliciano</u> Phone / Fax/Email: <u>787-426-1597</u> Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> Analyzed By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u> AIHA Lab ID: <u>199763</u>	Project Name: <u># 1 Unit, Jorge Lucas Perez Valdivieso</u> Total Samples: <u>13</u> Job Number: <u>ENJ- 1161</u> Worker Name: <u>Luis N Ortiz</u> Worker ID: <u>ASB-0414-0117-AW</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
--	---

Project Description: Cleaning of room # 6 and Big basketball court.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM	Air		
JS23071410	Jul-23-14	1161-230714-ASB-JS-10	In the BasketBall Area (North) Open Area	LV-2022	7:40	12:05	2.5	2.5	2.5	662.5	X			265	EX
JS23071411	Jul-23-14	1161-230714-ASB-JS-11	In the BasketBall Area (North) Open Area	LV-2022	13:30	15:54	2.5	2.4	2.4	345.6	X			144	EX
JS23071412	Jul-23-14	1161-230714-ASB-JS-12	In the BasketBall Area (South) Open Area	LV-2019	7:41	12:06	2.5	2.5	2.5	662.5	X			265	EX
JS23071413	Jul-23-14	1161-230714-ASB-JS-13	In the BasketBall Area (South) Open Area	LV-2019	13:31	15:58	2.5	2.3	2.3	338.1	X			147	EX

Turn Around Time: Normal: 7 days X Rush: 24 hours Rush: 16 hours

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-23-14						Jul-23-14



ALTOL ENVIRONMENTAL SERVICES, INC.
PO BOX 359 MERCEDITA, PR 00715-0359
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS




Customer Name: Homeca Recycling and Demolition's	Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso
Contact: Melvin Feliciano	Total Samples: 13 Job Number: ENJ-1161
Phone / Fax/Email: 787-426-1597	Custody Record #:
Sampling Date: Jul-23-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jul-24-14
Delivery By: Jose A Santos	Received Date: Jul-24-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analized By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: ASB-0414-0117-AW
Worker Name: Luis N Ortiz	Worker ID: N/A
Worker Name: N/A	Worker ID: N/A
Worker Name: N/A	Worker ID: N/A
Worker Name: N/A	Worker ID: N/A

Project Description: Cleaning of room # 6 and Big basketball court.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-230714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-230714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-230714-ASB-JS-03	Luis N Ortiz, Cleaning Room # 6	E	7:28	7:59	1.6	49.6	100	8.5	10.8	0.0840	0.0544	0.0840	< 0.0357
1161-230714-ASB-JS-04	Luis N Ortiz, Cleaning Room # 6	PRCE	8:00	11:53	1.6	372.8	100	25.5	32.5	0.0335	0.0072	0.0335	
1161-230714-ASB-JS-05	Luis N Ortiz, Cleaning Room # 6	PRCE	13:20	15:40	1.5	210.0	100	20.5	26.1	0.0479	0.0129	0.0479	
1161-230714-ASB-JS-06	Inside Room # 6	CE	7:29	11:54	2.5	662.5	100	17	21.7	0.0126	0.0041	0.0126	< 0.0125
1161-230714-ASB-JS-07	Inside Room # 6	CE	13:21	15:41	2.4	336.0	100	13	16.6	0.0190	0.0080	0.0190	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
--	---	--	-------------------



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS



Customer Name: Homeca Recycling and Demolition's Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-23-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analized By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Luis N Ortiz Worker Name: N/A Worker Name: N/A Worker Name: N/A	Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso Total Samples: 13 Job Number: ENJ-1161 Custody Record #: Collected ID: ASB-0912-0558-MS Delivery Date: Jul-24-14 Received Date: Jul-24-14 AIHA Lab ID: 199763 Worker ID: ASB-0414-0117-AW Worker ID: N/A Worker ID: N/A Worker ID: N/A
--	---

Project Description:	Cleaning of room # 6 and Big basketball court.
-----------------------------	--

Date: Jul-23-14						Date:							
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-230714-ASB-JS-08	Outside Room # 6 (Decom)	OS	7:30	11:55	2.5	662.5	100	6.5	8.3	0.0048	0.0041	0.0048	0.0027
1161-230714-ASB-JS-09	Outside Room # 6 (Decom)	OS	13:22	15:42	2.3	322.0	100	9.5	12.1	0.0145	0.0084	0.0145	
1161-230714-ASB-JS-10	In the BasketBall Area (North) Open Area	EX	7:40	12:05	2.5	662.5	100	37	47.1	0.0274	0.0041	0.0274	
1161-230714-ASB-JS-11	In the BasketBall Area (North) Open Area	EX	13:30	15:54	2.4	345.6	100	31	39.5	0.0440	0.0078	0.0440	
1161-230714-ASB-JS-12	In the BasketBall Area (South) Open Area	EX	7:41	12:06	2.5	662.5	100	38.5	49.0	0.0285	0.0041	0.0285	
1161-230714-ASB-JS-13	In the BasketBall Area (South) Open Area	EX	13:31	15:58	2.3	338.1	100	45	57.3	0.0653	0.0080	0.0653	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: Jul-23-14		Date:	

Customer Name: <u>Homeca Recycling and Demolition's</u> Contact: <u>Melvin Feliciano</u> Phone / Fax/Email: <u>787-426-1597</u> Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> Analyzed By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u> AIHA Lab ID: <u>199763</u>	Project Name: <u># 1 Unit, Jorge Lucas Perez Valdivieso</u> Total Samples: <u>13</u> Job Number: <u>ENJ- 1161</u> Worker Name: <u>Hector Montañez</u> Worker ID: <u>ASB-1013-0416-AW</u> Worker Name: <u>Jose L Sierra</u> Worker ID: <u>ASB-1113-0477-AW</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
--	---

Project Description: Cleaning of room # 6 and Bag Out.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS24071401	Jul-24-14	1161-240714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS24071402	Jul-24-14	1161-240714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS24071403	Jul-24-14	1161-240714-ASB-JS-03	Hector Montañez, Cleaning Room # 6	LV-5093	7:20	7:51	1.6	1.6	1.6	49.6	X			31	E
JS24071404	Jul-24-14	1161-240714-ASB-JS-04	Hector Montañez, Cleaning Room # 6	LV-5093	7:52	11:56	1.6	1.6	1.6	390.4	X			244	PRCE
JS24071405	Jul-24-14	1161-240714-ASB-JS-05	Hector Montañez, Cleaning Room # 6	LV-5093	13:21	15:36	1.6	1.5	1.5	202.5	X			135	PRCE
JS24071406	Jul-24-14	1161-240714-ASB-JS-06	Jose L Sierra, Bag Out	LV-5087	7:54	12:00	2.5	2.5	2.5	615.0	X			246	PRCE
JS24071407	Jul-24-14	1161-240714-ASB-JS-07	Jose L Sierra, Bag Out	LV -5087	13:26	15:02	2.5	2.3	2.3	220.8	X			96	PRCE
JS24071408	Jul-24-14	1161-240714-ASB-JS-08	Inside Room # 6	LV-5093	7:47	11:57	2.5	2.5	2.5	625.0	X			250	CE
JS24071409	Jul-24-14	1161-240714-ASB-JS-09	Inside Room # 6	LV-5093	13:22	15:37	2.5	2.4	2.4	324.0	X			135	CE

Turn Around Time: Normal: 7 days X Rush: 24 hours Rush: 16 hours


Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-24-14						Jul-24-14

Customer Name: <u>Homeca Recycling and Demolition's</u> Contact: <u>Melvin Feliciano</u> Phone / Fax/Email: <u>787-426-1597</u> Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> Analized By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u> AIHA Lab ID: <u>199763</u>	Project Name: <u># 1 Unit, Jorge Lucas Perez Valdivieso</u> Total Samples: <u>13</u> Job Number: <u>ENJ- 1161</u> Worker Name: <u>Hector Montañez</u> Worker ID: <u>ASB-1013-0416-AW</u> Worker Name: <u>Jose L Sierra</u> Worker ID: <u>ASB-1113-0477-AW</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
--	--

Project Description: Cleaning of room # 6 and Bag Out.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS24071410	Jul-24-14	1161-240714-ASB-JS-10	Outside Room # 6	LV-2022	7:48	11:58	2.5	2.5	2.5	625.0	X			250	OS
JS24071411	Jul-24-14	1161-240714-ASB-JS-11	Outside Room # 6	LV-2022	13:23	15:38	2.5	2.4	2.4	324.0	X			135	OS
JS24071412	Jul-24-14	1161-240714-ASB-JS-12	Outside (Dumpster)	LV-2019	7:55	12:10	2.5	2.5	2.5	637.5	X			255	OS
JS24071413	Jul-24-14	1161-240714-ASB-JS-13	Outside (Dumpster)	LV-2019	13:28	15:05	2.5	2.4	2.4	232.8	X			97	OS

Turn Around Time: Normal: 7 days <u> X </u> Rush: 24 hours <u> </u> Rush: 16 hours <u> </u>							
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:	
Jose A Santos						Jose A Santos	
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	
Jul-24-14						Jul-24-14	



ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS




Customer Name: Homeca Recycling and Demolition's Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-24-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Hector Montañez Worker Name: Jose L Sierra Worker Name: N/A Worker Name: N/A	Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso Total Samples: 13 Job Number: ENJ-1161 Custody Record #: Collected ID: ASB-0912-0558-MS Delivery Date: Jul-25-14 Received Date: Jul-25-14 AIHA Lab ID: 199763 Worker ID: ASB-1013-0416-AW Worker ID: ASB-1113-0477-AW Worker ID: N/A Worker ID: N/A
---	--

Project Description: Cleaning of room # 6 and Bag Out.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-240714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-240714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-240714-ASB-JS-03	Hector Montañez, Cleaning Room # 6	E	7:20	7:51	1.6	49.6	100	6.5	8.3	0.0643	0.0544	0.0643	< 0.0288
1161-240714-ASB-JS-04	Hector Montañez, Cleaning Room # 6	PRCE	7:52	11:56	1.6	390.4	100	20.5	26.1	0.0258	0.0069	0.0258	
1161-240714-ASB-JS-05	Hector Montañez, Cleaning Room # 6	PRCE	13:21	15:36	1.5	202.5	100	17	21.7	0.0412	0.0133	0.0412	
1161-240714-ASB-JS-06	Jose L Sierra, Bag Out	PRCE	7:54	12:00	2.5	615.0	100	36	45.9	0.0287	0.0044	0.0287	< 0.0276
1161-240714-ASB-JS-07	Jose L Sierra, Bag Out	PRCE	13:26	15:02	2.3	220.8	100	29	36.9	0.0644	0.0122	0.0644	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
--	-----------------------	--	-----------------------

Customer Name: Homeca Recycling and Demolition's Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-24-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Hector Montañez Worker Name: Jose L Sierra Worker Name: N/A Worker Name: N/A						Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso Total Samples: 13 Job Number: ENJ-1161 Custody Record #: Collected ID: ASB-0912-0558-MS Delivery Date: Jul-25-14 Received Date: Jul-25-14 AIHA Lab ID: 199763 Worker ID: ASB-1013-0416-AW Worker ID: ASB-1113-0477-AW Worker ID: N/A Worker ID: N/A							
Project Description: Cleaning of room # 6 and Bag Out.													
Date: Jul-24-14						Date:							
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-240714-ASB-JS-08	Inside Room # 6	CE	7:47	11:57	2.5	625.0	100	18	22.9	0.0141	0.0043	0.0141	0.0074
1161-240714-ASB-JS-09	Inside Room # 6	CE	13:22	15:37	2.4	324.0	100	14.5	18.5	0.0219	0.0083	0.0219	
1161-240714-ASB-JS-10	Outside Room # 6	OS	7:48	11:58	2.5	625.0	100	5	6.4	0.0039	0.0043	< 0.0043	
1161-240714-ASB-JS-11	Outside Room # 6	OS	13:23	15:38	2.4	324.0	100	4.5	5.7	0.0068	0.0083	< 0.0083	
1161-240714-ASB-JS-12	Outside (Dumpster)	OS	7:55	12:10	2.5	637.5	100	25	31.8	0.0192	0.0042	0.0192	
1161-240714-ASB-JS-13	Outside (Dumpster)	OS	13:28	15:05	2.4	232.8	100	19.5	24.8	0.0411	0.0116	0.0411	
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.													
Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			Signature: 			Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			Signature:				
Date: Jul-24-14						Date:							

Customer Name: <u>Homeca Recycling and Demolition's</u> Contact: <u>Melvin Feliciano</u> Phone / Fax/Email: <u>787-426-1597</u> Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> Analyzed By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u> AIHA Lab ID: <u>199763</u>	Project Name: <u># 1 Unit, Jorge Lucas Perez Valdivieso</u> Total Samples: <u>13</u> Job Number: <u>ENJ- 1161</u> Worker Name: <u>Ederick Caquias</u> Worker ID: _____ Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u> Worker Name: <u>N/A</u> Worker ID: <u>N/A</u>
--	--

Project Description: Re Cleaning of room # 9 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes	SAMPLE TYPE
					START	STOP	Initial	Final	Avg.		PCM	TEM			
JS25071401	Jul-25-14	1161-250714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---	FB
JS25071402	Jul-25-14	1161-250714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---	FB
JS25071403	Jul-25-14	1161-250714-ASB-JS-03	Ederick Caquias, Re,cleaning Room # 9	LV-1057	10:43	11:15	1.6	1.6	1.6	51.2	X			32	E
JS25071404	Jul-25-14	1161-250714-ASB-JS-04	Ederick Caquias, Re,cleaning Room # 9	LV-1057	11:16	11:56	1.6	1.6	1.6	64.0	X			40	PRCE
JS25071405	Jul-25-14	1161-250714-ASB-JS-05	Ederick Caquias, Re,cleaning Room # 9	LV-1057	13:22	15:36	1.6	1.5	1.5	201.0	X			134	PRCE
JS25071406	Jul-25-14	1161-250714-ASB-JS-06	Inside Room # 9	LV-5087	10:44	11:57	2.5	2.5	2.5	182.5	X			73	CE
JS25071407	Jul-25-14	1161-250714-ASB-JS-07	Inside Room # 9	LV -5087	13:24	15:38	2.5	2.3	2.3	308.2	X			134	CE
JS25071408	Jul-25-14	1161-250714-ASB-JS-08	Outside Room # 9 (Decom)	LV-1065	10:45	11:58	2.5	2.5	2.5	182.5	X			73	OS
JS25071409	Jul-25-14	1161-250714-ASB-JS-09	Outside Room # 9 (Decom)	LV-1065	13:25	15:39	2.5	2.4	2.4	321.6	X			134	OS

Turn Around Time: Normal: 7 days X Rush: 24 hours _____ Rush: 16 hours _____

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-25-14						Jul-25-14

Customer Name: Homeca Recycling and Demolition's Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-25-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Ederick Caquias Worker Name: N/A Worker Name: N/A Worker Name: N/A						Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso Total Samples: 13 Job Number: ENJ-1161 Custody Record #: Collected ID: ASB-0912-0558-MS Delivery Date: Jul-28-14 Received Date: Jul-28-14 AIHA Lab ID: 199763 Worker ID: 0 Worker ID: N/A Worker ID: N/A Worker ID: N/A					
Project Description: Re Cleaning of room # 9 .											


Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-250714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-250714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-250714-ASB-JS-03	Ederick Caquias, Re,cleaning Room # 9	E	10:43	11:15	1.6	51.2	100	5	6.4	0.0479	0.0527	< 0.0527	< 0.0256
1161-250714-ASB-JS-04	Ederick Caquias, Re,cleaning Room # 9	PRCE	11:16	11:56	1.6	64.0	100	18	22.9	0.1379	0.0422	0.1379	
1161-250714-ASB-JS-05	Ederick Caquias, Re,cleaning Room # 9	PRCE	13:22	15:36	1.5	201.0	100	15.5	19.7	0.0378	0.0134	0.0378	
1161-250714-ASB-JS-06	Inside Room # 9	CE	10:44	11:57	2.5	182.5	100	11	14.0	0.0296	0.0148	0.0296	< 0.0105
1161-250714-ASB-JS-07	Inside Room # 9	CE	13:24	15:38	2.3	308.2	100	13.5	17.2	0.0215	0.0088	0.0215	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal
 T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229
--	-----------------------	--

Customer Name: Homeca Recycling and Demolition's Contact: Melvin Feliciano Phone / Fax/Email: 787-426-1597 Sampling Date: Jul-25-14 Analytical Method: NIOSH 7400 Collected By: Jose A Santos Delivery By: Jose A Santos Received By: Jose A Santos Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc. Worker Name: Ederick Caquias Worker Name: N/A Worker Name: N/A Worker Name: N/A						Project Name: # 1 Unit, Jorge Lucas Perez Valdivieso Total Samples: 13 Job Number: ENJ-1161 Custody Record #: Collected ID: ASB-0912-0558-MS Delivery Date: Jul-28-14 Received Date: Jul-28-14 AIHA Lab ID: 199763 Worker ID: 0 Worker ID: N/A Worker ID: N/A Worker ID: N/A							
Project Description: Re Cleaning of room # 9 .													
Date: Jul-25-14						Date:							
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-250714-ASB-JS-08	Outside Room # 9 (Decom)	OS	10:45	11:58	2.5	182.5	100	7.5	9.6	0.0202	0.0148	0.0202	0.0031
1161-250714-ASB-JS-09	Outside Room # 9 (Decom)	OS	13:25	15:39	2.4	321.6	100	5	6.4	0.0076	0.0084	< 0.0084	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627		Signature: 	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229		Signature:
Date: Jul-25-14		Date:			